Mercedes-Benz Antos 2532 6x2*4, Crane



Poulsen Biler ApS Haarup skovvej 7, Haarup 8600 Silkeborg

Sælger Poulsen Trucks & Trailers ApS Mail@poulsentrucks.com

Tyres

- +45 74 67 11 12
- +45 74 67 11 12

APPROXIMATE TO SERVICE AND ADDRESS OF THE PARTY OF THE PA	
Basis	
Туре	Truck
Aksel	6x2*4
Stand	Fine
Registration	
Year	2018
Reg. date	14-09-2018
Last inspection	12-09-2023
Ref. no.	7522
Engine and transmission	
HP	320
KM	403.000
Gear box	EPS aut shift
EURO type	6
number of tank	1
Litre of tank	300
Adblue tank liter	60

Suspension	
front, parable	✓
back, air	v
Weight	
Loading capacity	12.220kg
Total weight	26.000kg
Empty weight	13.780kg
Brakes	
Disk brake	✓
ABS	✓
Chassis	
Wheelbase	6.100mm
Axel pressure, front	8.000kg
Axel pressure, back	19.000kg
Crane	
Tonne metre	18,5
Remote control	✓
Front mounted	✓
Discharge	3
Manufacture	Palfinger
Year	2018
ID Nummer	100429264

1st axle tyres L-R%	80-20
2nd axle tyres L-R%	40-60
3rd axle tyres L-R%	40-80
1st Axle Tyres size	385/55R22,5
2nd Axle Tyre Size	315/70R22,5
3rd Axle Tyre Size	385/55R22,5
Cab	
Mirror camera	~
back camera	✓
Walkie	~
Navigation	✓
Cabine heater	~
ACC Distance Radar	✓
Air conditioning	~
Automatic emergency brake 🔻	
Lane Assist	~
Radio	✓
Load indicator	✓

Beskrivelse

Mercedes Antos 2532 6x2/4 euro 6

8850 mm galvanized fixed bed - 800 mm aluminum sides and chin grab - rear bumper with side-hinged rear doors - veneer bottom - lashing holes in the edge of the bed and holes for walking sticks on each side

and in the middle - 2 large tool boxes and 1 open straw box - long magazine box under the bed between long sides approx. H $68 \text{ mm} \times \text{W} 14 \text{ mm}$

Hydraulic extension bumper to 1400mm. thus lan is driven with long goods crane with a pipeline for rotor - remote control - reach 14.45 mtr = lifts 1130 kg

6100 mm axle distance - hydraulically rotatable bogie - air conditioning - engine/cabin heater - rear camera - cyclist's camera - Flash lights front+rear + sides - rotor flashing light silt on roof - LED work lights on rear wall - step boxes + rear

Appears in well maintained and serviced condition

Contact Scanvo +45 87244370 - or via email salg@scanvo.dk

Visit our website www.scanvo.dk - always more than 300 newer: trucks - trailers - trailers - containers + cranes much more transport equipment













